

SECRET

Contract [REDACTED]

25X1

FY-69 Quarterly Report No. 2

DDR-Dupe

PAR 249

30 Nov 68

SUBJECT: [REDACTED] Precision Enlarger Prototype (BPE) Operational
Improvements and Maintenance

25X1

TASK/PROBLEM

1. Provide photographic enlarger maintenance at the customer's facility for one [REDACTED] Precision Enlarger (BPE) and three 10-20-40X Enlargers.

25X1

DISCUSSION

2. Contractor personnel visited the customer's facility twice during the report period and while there performed the following maintenance efforts.

a. During week of 9 September 1968:

(1) The lens barrels were found to be loose in the focus barrels. These were tightened and refocused, and a complete photographic check was made.

b. During week of 28 October 1968:

(1) The non-steering rollers (P/N 1-023-E-405 and 406) were found to be defective. Replacement rollers were sent and installed and tracking tests were satisfactory.

(2) The lamphouse platen assembly (P/N 1-023-C-330) was replaced.

(3) Vertical drive limit switches were installed and checked out OK.

(4) Sealed all lens barrels with RTV.

PLANNED ACTIVITY

3. Perform monthly preventive maintenance on the BPE and the 10-20-40X Enlargers during the week of 9 December 1968.

SECRET

GROUP 1
EXCLUDED FROM AUTOMATIC DOWNGRADING
AND DECLASSIFICATION